Statement Of Work For Rebuild of the Radio Set, AN/MRC-142 NSN 5895-01-333-3040

SOW-06-PMM122-09543A-1/1

Prepared by
Marine Corps Systems Command, C4IHF
Marine Corps Logistics Bases, Albany, Georgia

# **Table of Contents**

Section	n/Paragraph	Page
1.0	Scope	1
1.1	Background	1
2.0	Applicable Documents	1
2.1	Military Standards	1
2.2	Other Government Documents and Publications	1
2.3	Industry Standards	2
3.0	Requirements	3
3.1	General Tasks	3
3.2	Detail Tasks	3
3.2.1	Phase I - Pre-Induction	3
3.2.2	Phase II - Rebuild	3
3.2.3	Phase III - Inspection, Testing and Acceptance	4
3.2.4	Packaging, Handling, Storage and Transportation (PHS&T)	4
3.3	Configuration Control	4
3.4	Government Furnished Equipment (GFE)/Government	4
	Furnished Materiel (GFM)	
3.5	Contractor Furnished Materiel	5
3.6	Electrostatic Discharge (ESD) Control Program	5
3.7	Electromagnetic Environmental Effects (E <sup>3</sup> ) Procedures	5
3.8	Quality Assurance Provisions	5
3.9	Acceptance	5
3.10	Rejection	5
Appen	dix A Pre-Induction Checklist	A-1

## STATEMENT OF WORK FOR THE Rebuild of the Radio Set, AN/MRC-142 NSN 5895-01-333-3040

- 1.0. <u>Scope</u>. This Statement of Work (SOW) establishes, sets forth tasks and identifies the work efforts that shall be performed by the Contractor (for purposes of this SOW, Contractor is defined as the commercial or government entity performing the rebuild) in the rebuild effort of the Radio Set, AN/MRC-142 (hereafter known as the Radio Set). This document contains requirements to restore the Radio Set to Condition Code "A." Condition Code "A" is defined as "serviceable/issuable without qualification, new, used, repaired or reconditioned materiel which is serviceable and issuable to all customers without limitation or restriction, including materiel with more than six months shelf-life remaining."
- 1.1 <u>Background</u>. Rebuild is defined as "That maintenance technique to restore an item to a standard as near as possible to original or new condition in appearance, performance, and life expectancy. This is accomplished through a maintenance technique or complete disassembly of the item, inspection of all parts or components, repairs or replacement of worn or unserviceable elements using original manufacturing tolerances and/or specifications and subsequent reassembly of the items."
- 2.0 Applicable Documents. The following documents form a part of this SOW to the extent specified. Unless otherwise specified, the issues of these documents are those listed in the Department of Defense Index of Specifications and Standards (DoDISS) and supplement thereto which is in effect on the date of solicitation. In the event of conflict between the documents referenced herein and the contents of this SOW, the contents of this SOW shall be the superseding requirement.

#### 2.1 Military Standards

MIL-STD-129 DoD Standard Practice for Military Marking

MIL-STD-2073-1D DoD Standard Practice for Military Packaging

## 2.2 Other Government Documents and Publications.

TM 09543A-12	Maintenance Manual	PCN 184 095430 00
TM 09543A-35/1, Vol. I	Radio Terminal Set, AN/MRC-142	PCN 184 095433 00
TM 09543A-35/1, Vol. I, w/CH001	Radio Terminal Set, AN/MRC-142 CH01	PCN 184 095433 01
TI-5820-25/22A	Comm Equip on Marine Corps Platforms	PCN 168 047801 00

2.3

TM 09543A-35/2, Vol. II w/CH001	Radio Terminal Set, AN/MRC-142 CH01	PCN 184 095434 00 PCN 184 095434 01			
SL-3-09543A w/CH001-03	Radio Terminal Set AN/MRC-142 CH01-03	PCN 123 095430 00 PCN 123 095430 01-03			
SL-4-09543A w/CH001-05	Radio Set AN/MRC-142 CH01-05	PCN 124 095430 00 PCN 124 095430 01-05			
MI-2320-24/69	Soft top Brace on HMMWV	PCN 161 133656 00			
MI-09543A-35/1 Dtd 10 July 195	Radio Terminal Set 1601 AN/MRC-142	PCN 160 988750 00			
DOD 4000.25-1-M	Military Standard Requisitioning and Issue Procedures (MILSTRIP)				
Military Hanbooks (For Guidance)					
MIL-HDBK-61	Configuration Management (	Guidance			
Industry Standards					
JESD625-A	Requirements for Handling Electrostatic- Discharge-Sensitive (ESDS) Devices				
ANSI/ISO/ASQC Q9001-2000	Quality Management Systems-Requirements				
Industry Standards (For Guidance)					
ANSI/EIA-649	National Consensus Standard for Configuration Management				

Copies of Military Standards and Specifications are available from the DOD Single Stock Point, Document Automation and Production Service, Building 4/D, 700 Robbins Avenue, Philadelphia, PA 19111-5094, commercial telephone number (215) 697- 2179 or DSN 442-2179, or <a href="http://www.dodssp.daps.mil">http://www.dodssp.daps.mil</a>. Copies of other government documents and publications required by contractors in connection with specific SOW requirements shall be obtained through the Logistics Management Specialist: Marine Corps Systems Command (MCSC), Attn: Logistics Management Specialist (Code C4IHF), 814 Radford Blvd., Suite 20343, Albany, Georgia 31704-0343, commercial telephone number (229) 639- 6773 or DSN 567-6773. Copies of engineering drawings, if applicable, shall be obtained from Supply Chain Management Center, Attn: Code 583-1, 814 Radford Blvd., STE 20320, Albany, Georgia 31704-0320, commercial telephone number (229) 639-6476 or DSN 567-6476.

### 3.0 Requirements

- 3.1 General Tasks. In fulfilling the specified requirements, the Contractor shall:
- a. Provide materials, labor, equipment, facilities and missing/repair parts, necessary to inspect, diagnose, restore, test and calibrate the Radio Set. Upon completion of rebuild, the subject item shall be Condition Code "A."
- b. Conduct in-process and final on-site testing for witness by a MCSC (C4IHF), Albany, Georgia authorized representative.
- 3.2 <u>Detail Tasks</u>. The following tasks describe the different rebuild phases of the Radio Set.
- 3.2.1 <u>Phase I- Pre-Induction</u>. A pre-induction inspection analysis shall be performed for each Radio Set using the Contractor Facility's diagnosis, inspection and testing techniques to determine extent of work and parts required. These findings shall be annotated on the Pre-Induction Checklist (Appendix A).
- 3.2.2 <u>Phase II -Rebuild</u>. After pre-induction tests and inspections have been completed, repair of the Radio Set shall be accomplished in accordance with this SOW. Deficiencies noted on the Pre-Induction Checklist (Appendix A) during Phase I shall be repaired/replaced. Components or assemblies shall not be disassembled for replacement of parts unless that part has failed, or the component assembly wherein the part is located is disassembled for repair. Any Modification Instruction (MI) or Engineering Change Proposal (ECP) not previously applied shall be incorporated.
- a. <u>Data Plate</u>. Each repaired Radio Set shall have a rebuild data plate affixed to the location specified in MI-09543A-35/1 dated 10 July 1995: PCN 160 988750 00.

#### b. Hardware

- (1) Replace broken, unserviceable and/or missing hardware including nuts, bolts, screws, washers, turn lock fasteners, mandatory replacement items, safety, and one-time use items, etc., in accordance with this SOW. Unserviceable would include any of the above that failed to function properly.
- (2) Ensure proper hardware locking devices are present on all moving mechanical assemblies.
- (3) Hardware normally supplied with commercial parts shall be used unless specifically prohibited.

#### 3.2.3 Phase III - Inspection, Testing and Acceptance

- a. Contractor shall conduct inspection, testing and acceptance of the Radio Set shall be in accordance with TM 09543A-12, TM-09543A-35/1 Vol. I, TM-09543A-35/1 Vol. I w/ CH001, TM-09543A-35/2 Vol. II w/CH001, SL-3-09543A w/CH001-03, SL-4-09543A w/CH001-05, MI-2320-24/69 and TI-5820-25/22A. Insure that all current ECPs and MIs have been incorporated.
- b. The Contractor shall be responsible for conducting required tests and shall ensure all necessary personnel are notified prior to completion of the final acceptance. Acceptance tests shall be held at the contractor's facility. MCSC (C4IHF), Albany, Georgia authorized representative shall be given a minimum of two weeks notice prior to commencement of acceptance testing.
- c. The Contractor shall be responsible for correcting any deficiencies identified during inspection/testing. MCSC (C4IHF), Albany, Georgia authorized representative may require the Contractor to repeat tests or portions thereof, if the original tests fail to demonstrate compliance with this SOW.

## 3.2.4 Packaging, Handling, Storage and Transportation (PHS&T)

- a. The Contractor shall be responsible for preservation and packaging of item(s) being rebuilt under the terms of this Statement of Work. Items scheduled for long-term storage or shipment to overseas destinations shall be in accordance with Level "A"requirements of MIL-STD-2073-1D, Appendix A, Table A.VI., Electronic Equipment. Items scheduled for domestic shipment for immediate use or short- term storage shall be to Level "B" requirements.
  - b. Marking for shipment and storage shall be in accordance with MIL-STD-129.
- c. The Marine Corps will provide the contractor with the shipping address(es) for delivery of the repaired equipment. The contractor shall be responsible for arranging for shipment to the pre-designated site(s). The Marine Corps will be responsible for transportation costs associated with shipping the subject equipment to and from the Contractor.
- 3.3 <u>Configuration Control</u>. The contractor shall apply configuration procedures to establish configuration items. The contractor shall not implement configuration changes to an item's documented performance or design characteristics without receiving prior written authorization. If it is necessary to temporarily depart from the authorized configuration, the contractor shall prepare and submit a Request for Deviation. MIL-HDBK-61 and ANSI/EIA-649 Provide guidance for preparing this configuration control document.
- 3.4 Government Furnished Equipment (GFE)/Government Furnished Materiel (GFM). The Management Control Activity (Code 571-1) will coordinate GFE/GFM requests and maintain a central control system on all government owned assets in the contractor's possession. The MCA will forward a GFE Accountability Agreement to the contractor for signature on an annual basis

to establish a chain of custody and identify property responsibilities for Marine Corps assets. The contractor is to acknowledge receipt of GFM to the MCA within 15 days of receipt. This can be done by mailing a copy of the DD1348 to: Materiel Management Department, Management Control Activity (Code 571-1), 814 Radford Blvd., STE 20320, Albany, GA 31704-0320 or faxing a copy to commercial telephone number (229)-639-5498 or DSN 567-5498.

- 3.5 <u>Contractor Furnished Materiel (CFM)</u>. The contractor may requisition materiel as required in the performance of the SOW through the DOD Supply System. DOD 4000.25-1-M (MILSTRIP) Chapter 11 provides guidance to contractors on the requisitioning process. The contractor's decision to utilize CFM procured from the DOD Supply System shall be based upon cost effectiveness, availability of materiel and the required completion/delivery date.
- 3.6 <u>Electrostatic Discharge (ESD) Control Program</u>. The contractor shall establish, implement and document an ESD control program following the guidelines provided in JESD625-A. ESD protective measures shall be used during manufacturing, handling, inspection, testing, marking, packaging, storing and transporting ESD sensitive components.
- 3.7 <u>Electromagnetic Environmental Effects (E3) Procedures</u>. The Contractor shall plan for and use proper (E3) control procedures in the rebuild process and shall utilize TI-5820-25/22A in conjunction with the detailed requirements specified in this document.
- 3.8 Quality Assurance Provisions. The Contractor shall provide and maintain a Quality System that, as a minimum, adheres to the requirements of ANSI/ISO/ASQC Q9001-2000, Quality Management Systems Requirements. The program shall ensure quality throughout all areas to include processing, assembly, inspection, testing, maintenance, and preparation for delivery and shipping. Unless otherwise specified in the contract, the contractor shall be responsible for performance of all inspection requirements. MCSC, (C4IHF), Albany reserves the right to perform any of the inspections set forth in the contract where such inspections are deemed necessary to assure products and services conform to the prescribed requirements. The Contractor shall provide an Inspection and Test Plan that will ensure the Radio Set will meet or exceed its original performance characteristics. Inspection Test Plan shall be sent to: Marine Corps Systems Command (Code C4IHF), Attn: Logistics Management Specialist, 814 Radford Blvd., Suite 20343, Albany, Georgia 31704-0343.
- 3.9 <u>Acceptance</u>. The performance of the Contractor and the quality of work delivered, including all equipment furnished and documentation written or compiled, shall be subject to in-process review and inspection during performance. Inspection may be accomplished in-plant or at any work site or location, and MCSC (Code C4IHF), Albany, GA representatives shall be permitted to observe the work or to conduct an inspection. Final inspection and acceptance testing shall be conducted at the Contractor's Facility. Final acceptance shall be conducted on 100 percent of items to verify that the units meet all requirements.
- 3.10 <u>Rejection</u>. Failure to comply with any of the specified requirements listed herein shall be reason for rejection by MCSC (Code C4IHF), Albany, representative. The Contractor shall, at no

additional cost to MCSC, (Code C4IHF), Albany, Georgia, correct the deficiencies and repeat the verification until an acceptable compliance with acceptance test procedures is demonstrated.

## Pre-Induction Checklist Radio Set, AN/MRC-142

- 1. Using the following criteria, inspect the items listed below.
  - a. Refer to SOW-835-2-08770A-2/1 for HMMWV inspection checklist.
  - b. Inspect for dirt, dust, sand, etc.
  - c. Inspect for rust and/or corrosion damage.
  - d. Inspect for any physical damage to different units. (cuts, dents, cracks, broken pins, etc.)
  - e. Ensure that all screws, washers, nuts, bolts, etc. are attached.
  - f. Inspect for dry rot on all rubber and plastic components.
  - g. Ensure that all covers and caps are attached.
  - h. Ensure that all knobs, switches and breakers operate freely and properly.
  - I. Inventory for accountability.

S - Serviceable		U - Unserviceable	<b>M</b> - N	Missing	
Rac	k Assembly and Ha	ardware:	Qty	Condition	Remarks
1.	Rack		1		
2.	CDA clamps		4		
3.	RT Clamps		4		
4.	Thumbscrews,		8		
5.	Ground straps		7		
6.	PDP hold down sc	rews	4		
7.	KY-57 mount and	Hardware	1		
8.	V Rubber Mast Bu	mper	2		
9.	Mast Hold Down S	Straps	2		
10.	FOCS Hold Down	Straps	2		
11.	Mast Pad Straps		2		
12.	RF Cable		2		
Cab	ole Assemblies:				
1.		(PDP J8 - CDA2 J1)	1		
2.	Pwr CDA #1 W4	(PDP J8 - CDA1 J1)	1		
3.	Pwr Cable RT #1	W2 (PDP J6 - RT1 J2/J3)	1		
4.	Pwr Cable RT #2 V	W5 (PDP J7 - RT2 J2/J3)	1		
5.	Repeater Cable W	12 (CDA1 J6 - CDA2 J6)	1		
6.	Baseband Cable W	16 (CDA2 J7 - RT B.B.)	1		
7.	KY-57 BLK W9 (0	CDA J2 - KY-57)	1		
8.	TED Cable 2 W11	(CDA2 J3 - TED 2)	1		
9.	TED Cable 1 W10	(CDA2 J4 - TED 2)	1		
10.	TED Cable 2 W13	(CDA1 (B)J4 - TED 1)	1		
11.	TED Cable 1 W14	(CDA1 (R)J4 - TED 1)	1		

12.	KY-57 RED W8 (CDA J5 -KY-57)	1		
13.	Baseband Cable W15 (CDA J7 - RT B.B.)	1		
14.	Pwr Cable W1	1		
			-	
<u>CD</u>	A #1 Front Panel Inventory/Serviceability check:			
1.	Handset Connector, and cover, J9			
3.	Trunk Loop Rate Switch			
4.	Volume Control			
5.	Orderwire Mode Switch			
6.	AVOW and DVOW Call Lamp			
7.	Orderwire Call Switch			
8.	Timing Select Switch			
9.	Operating Mode Control Switch			
10.	Loopback Selector Switch			
11.	Power On/Off Circuit Breaker			
12.	Audible Alarm Speaker			
13.	Reset Switch			
14.	Alarm Status Monitors			
15.	Test Switch			
16.	NSW Indicator			
17.	FRM Indicator			
18.	INCM Indicator			
19.	FLT Indicator			
20.	PWR Indicator			
$CD_{I}$	4 #1 Rear Panel Inventory/Serviceability Check:			
1.	Power Connector, and cover, J1		-	
2.	KY-57 Black, and cover, J2			
3.	KG-194A Black, and cover, J3			
4.	KG-194A Red, and cover, J4			
5.	KY-57 Red, and cover, J5			
6.	RPTR, and cover, J6			
7.	Radio, and cover, J7			
8.	Ground, E1			
9.	Cable conn. and cover, J8			
<u>CD</u>	A #2 Front Panel Inventory/Serviceability check:			
1.	Handset Connector, and cover, J9			
3.	Trunk Loop Rate Switch			
4.	Volume Control			
5.	Orderwire Mode Switch			
6.	AVOW and DVOW Call Lamp			
7.	Orderwire Call Switch			

8.	Timing Select Switch		
9.	Operating Mode Control Switch		
10.	Loopback Selector Switch		
11.	Power On/Off Circuit Breaker		
12.	Audible Alarm Speaker		
13.	Reset Switch		
14.	Alarm Status Monitors		
15.	Test Switch		
16.	NSW Indicator		
17.	FRM Indicator		
18.	INCM Indicator		·
19.	FLT Indicator		
20.	PWR Indicator		
	A #2 Rear Panel Inventory/Serviceability Check:		
1.	Power Connector, and cover, J1		
2.	KY-57 Black, and cover, J2		
3.	KG-194A Black, and cover, J3		
4.	KG-194A Red, and cover, J4		-
5.	KY-57 Red, and cover, J5		
6.	RPTR, and cover, J6	-	
7.	Radio, and cover, J7		
8.	Ground, E1		
9.	Cable conn. and cover, J8		<del></del>
DDI	9 #1 Inventory/Sarviceshility Checks		
г <u>рг</u> 1.	*#1 Inventory/Serviceability Check: Frequency Meter		
	AC Voltage Meter		
2. 3.	AC Power Indicator (green)		
	DC Power Indicator (green)		
4. 5	, , , , , , , , , , , , , , , , , , ,		
5.	DC Voltage Meter		
6. 7	RVS PLRT, Reverse Polarity Indicator (red) DC Circuit Breaker	<del></del>	
7. •			
8. n	AC/DC Circuit Breaker, Mechanical Interlock AC Circuit Breaker		
9. 10.	DC Input, J2	<del></del>	
10. 11.	AC Input, J1		
	AC/DC Black PWR to UHF Radio #1, J6		
12.	•		
13.	AC/DC Black PWR to UHF Radio #2, J7		
14.	DC Red PWR to TD-1234 RMC, J3-RMC-DC		
15.	AC Red PWR to TD-1234 RMC, J4-RMC-AC		
16.	AC/DC Pleak PWR to FOCS, J5 FOCS		
17.	AC/DC Black PWR to CDA #1, 18		
18.	AC/DC Black PWR tp CDA #1, J8		
19.	Ground Connection, E1		

PDI	**P #2 Inventory/Serviceability Check:		
1.	Frequency Meter		
2.	AC Voltage Meter		
3.	AC Power Indicator (green)		
4.	DC Power Indicator (green)		
5.	DC Voltage Meter		
6.	RVS PLRT, Reverse Polarity Indicator (red)		
7.	DC Circuit Breaker		
8.	AC/DC Circuit Breaker, Mechanical Interlock		
9.	AC Circuit Breaker		
10.	DC Input, J2		
11.	AC Input, J1	<u></u>	
12.	AC/DC Black PWR to UHF Radio #1, J6		
13.	AC/DC Black PWR to UHF Radio #2, J7		
14.	DC Red PWR to TD-1234 RMC, J3-RMC-DC		
15.	AC Red PWR to TD-1234 RMC, J4-RMC-AC		
16.	AC/DC Red PWR to FOCS, J5 FOCS		
17.	AC/DC Black PWR to CDA #2, J9		
18.	AC/DC Black PWR to CDA #1, J8	***************************************	
19.	Ground Connection, E1	<del></del>	
	Ground Commonion, 21		
RT:	#1 Inventory/Serviceability check:		
1.	Buzzer, Alarm		
2.	Antenna Connector, and cover, J12		
3.	Pressure Relief Valve		
4.	Display/Alarm Indicator		
5.	TX/REC Freq Display		
6.	BASEBAND Connector, and cover, J3	<del></del>	
7.	SYSCON Connector, and cover, J4		
7. 8.	EOW Connector, and cover, J5		
9.	AUDIO Connector,		
). 10.	Ground Terminal		
11.	Keypad		
12.	IN-AC Connector, and cover, J10		
13.	DC-PWR Connector, and cover, J11		
13. 14.	Power On Switch		
15.	On Indicator		
15. 16.	Chassis and Hardware		
IU.	Chassis and Haidware		
RT:	#2 Inventory/Serviceability check:		
1.	Buzzer, Alarm		
-	, = ======		

3.	Pressure Relief Valve			
4.	Display/Alarm Indicator			
5.	TX/REC Freq Display			
6.	BASEBAND Connector, and cover, J3			
7.	SYSCON Connector, and cover, J4			
8.	EOW Connector, and cover, J5		<del></del>	
9.	AUDIO Connector,			
10.	Ground Terminal			
11.	Keypad			
12.	IN-AC Connector, and cover, J10			
13.	DC-PWR Connector, and cover, J11			
14.	Power On Switch			
15.	On Indicator			
16.	Chassis and Hardware			
Ant	onna Assambly #1 Inventory/Sarvigashility Charles			
1.	enna Assembly #1 Inventory/Serviceability Check: Feed Assembly	1		
2.	Reflector Assembly	1		
3.	OffSet Adapter	1	<del></del>	
<i>3</i> . 4.	Dust Caps, feed assembly	2		
4.	Dust Caps, feed assembly	2		
Anto	enna Assembly #2 Inventory/Serviceability Check:			
1.	Feed Assembly	1		
2.	Reflector Assembly	1		
3.	Off Set Adapter	1		
4.	Dust Caps, feed assembly	2		
Ante	enna Mast Assembly #1 Inventory/Serviceability Ch	eck:		
1.	Mast Section, Telescoping, 11 sections	1		
2.	Guy Ring Assemblies, p/o mast sections,	4		
3.	Clamp Assemblies, p/o mast sections,	10		
4.	Carrying Handle, p/o mast section,	1	<del></del>	
5.	Compass, p/o carrying handle,	1		
6.	Level, p/o carrying handle,	1		
A 4 -	nuna Magt Aggamble #2 Inventors/Corrigoshility Ch	ممادر		
<u>Anu</u>	enna Mast Assembly #2 Inventory/Serviceability Ch Mast Section, Telescoping, 11 sections			
2.	Guy Ring Assemblies, p/o mast sections,	1 4		
	Clamp Assemblies, p/o mast sections,			
3. 1	Carrying Handle, p/o mast section,	10 1		
4. 5.	Compass, p/o carrying handle,	1		
5. 6.	Level, p/o carrying handle,	1		
υ.	Level, pro carrying nandie,	1		
Mas	t Accessory Kit #1 Inventory/Serviceability Check:			
1	Mast Accessory Bag	1		

2.	Hammer	1	
3.	Base Spike	1	 
4.	Guy Line Anchors	12	 
5.	Guy Line Reels	2	 
6.	Guy Lines, p/o guy line reels, (Blue)	4	 
7.	Guy Lines, p/o guy line reels, (Green)	4	 
8.	Guy Lines, p/o guy line reels, (Black)	4	 
9.	Guy Lines, p/o guy line reels, (Brown)	4	 
10.	Azimuth Locking Pin	1	 
11.	Wrench, 10mm	1	 
Mas	t Accessory Kit #2 Inventory/Serviceability Check:		
1.	Mast Accessory Bag	1	
2.	Hammer	1	 
3.	Base Spike	1	
4.	Guy Line Anchors	12	
5.	Guy Line Reels	2	
6.	Guy Lines, p/o guy line reels, (Blue)	4	 
7.	Guy Lines, p/o guy line reels, (Green)	4	 
8.	Guy Lines, p/o guy line reels, (Black)	4	
9.	Guy Lines, p/o guy line reels, (Brown)	4	
10.	Azimuth Locking Pin	1	 
11.	Wrench, 10mm	1	 
	,		 
Syst	em Accessory Kit #1 Inventory/Serviceability Check:		
1.	Accessory Bag	1	
2.	H-250 Handset	2	
3.	RMC Power Cable	1	
4.	FOCS AC Power Cable	1	
5.	FOCS DC Power Cable	1	
6.	TED Bypass Cable	2	 
7.	Repeater Cable	1	 
8.	Connector, Adapter, Series N	1	
9.	Dummy Load	1	 
10.	Cold Weather Finger	1	 
Syst	em Accessory Kit #2 Inventory/Serviceability Check:		
1.	Accessory Bag	1	
2.	H-250 Handset	2	 
3.	RMC Power Cable	1	 
<i>4</i> .	FOCS AC Power Cable	1	 
5.	FOCS DC Power Cable	1	 
6.	TED Bypass Cable	2	 
0. 7	Reneater Cable	1	 

SO	23 April 2003		
8.	Connector, Adapter, Series N	1	_
9.	Dummy Load	1	
10.	Cold Weather Finger	1	

# CONTRACT DATA REQUIREMENTS LIST

(1 Data Item)

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington readquarters Services, Directorate for Information Operations and Reports (0701-0188), 1215 Jefferson Davis Highway, Saite 1204, Arington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of aw, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

Please DU NOT RETURN your form to the above address. Send completed form to the Government Issuing Contracting Officer for the Contract/PR No. listed in Block E.

A. CONTRACT LINE I	ITEM NO.	B. EXHIBIT C. CATEGORY:  TDP TM OTHER								1
D. SYSTEM/ITEM		<u> </u>	E. CONTRACT/PR		F. CONTRA					
	, AN./MRC-142	,								
. DATA ITEM NO.	2. TITLE OF DATA ITEM		<u> </u>		3. SUBTITLE					17. PRICE GROU
					01	ty Control/Assurance	and I	nenect	ion	
A001		Inspectio	n and Test Pla		Quan	-				18. ESTIMATED
4. AUTHORITY (Data Acquis	sition Document No.)		5. CONTRACT REFEREN	ce Paragraph 3.8		6. REGURNARCORSYS (C4II	COM . HF)	Albany	y	TOTAL PRICE
	I-QCIC-81110	40 ENEQUES		12. DATE OF FIRST SUBMISSI	BN	14. DISTRIBUTION				i
7. DD 250 REQ DD	9. DIST STATEMENT REQUIRED	10. FREQUEN	ONE/R	See Blk 1		14. DISTRIBUTION		b. COPIES		
8. APP CODE		11. AS OF DA		13. DATE OF SUBSEQUENT		a. ADDRESSEÉ		Fin	al	
A. APP CODE	Α			Submission See Blk 1	6		Draft	Reg	Repro	1
16. REMARKS		_1				MCSC Alby (C4I)	0	1	0	i
Block 12 - Sul	bmit 30 days after and comment.	r contract	award by LT	Government req	uires 60					
days to review	and comment.		•							
Block 13 - Fir	nal due 30 days af DD250.	fter receip	ot of Governm	ent comments. Su	bmit					1
final plan by I	DD250.									:
Distribution S	tatement A: Appr	oved for	public release	, distribution is u	limited.					:
										!
										1
							<u> </u>			
							<b>ļ.</b>			
							<del> </del>	<u> </u>		İ
		-							-	!
							<del>                                     </del>		<b></b>	
										1:
							1			
										<b>]</b>
									<u> </u>	
									<b> </b>	
							ļ	<u> </u>	ļ	
								<b> </b>	<u> </u>	1
							<del> </del>	<del> </del>	<del> </del>	
								ļ		<b> </b>
							╁	<del> </del>	-	1
							┼	<del> </del>	<del> </del> -	<b>1</b> i
							+	1	<del></del>	1
ŀ							╅	<del>                                     </del>	+	1
1								1	1	1
							1	1	1	1
1							1	1		1:
				1		15. TOTAL	- (	) 1	0	]
G. PREPARED BY	7 1		H. DATE	I. APPROVED	ВҮ		J. DA	TE		1
12/1/1/	1 1 94			- 17 M	1	O(Z)		۸۵۰	22	
131.71	Her		7APR	03   121111	ال	1. Jourses	1	<u>APR</u>	<u>U3</u>	<b>.</b>
DD FORM 142	3-1. AUG 96 (EG)			PREVIOUS EDITION MAY	BE USED.		Page _	of	Page	es

### **CONTRACT DATA REQUIREMENTS LIST**

(1 Data Item)

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Department of Defense, Washington Headquarters Services, Directorate for Information Department of Defense, Washington and Teverson and Reports (0701-07188), 1215 Jefferson Davis Highway, Suite 1204, Affington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any pensity for failing to comply with a collection of information if it does not display a currently valid OMB control number.

Please DO NOT RETURN your form to the above address. Send completed form to the Government Issuing Contracting Officer for the Contract/PR No. listed in Block E.

A. CONTRACT LINE ITEM NO.  B. EXHIBIT  C. CATEGORY:  TDP  TM					OTHER	×				
D. SYSTEM/ITEM AN/M	RC-142 Radio Se	t	E. CONTRACT/PR		F. CONTRA					
1. DATA ITEM NO.	2. TITLE OF DATA ITEM				3. SUBTITLE	1/L				17. PRICE GROU
в001	Re	quest For	Deviation (R)	FD)		Configuration Ma	nageme	ent		
4. AUTHORITY (Data Acquis			5. CONTRACT REFEREN		<u> </u>	6. REQUIRING OFFICE				18. ESTIMATED
DI-C	CMAN-80640C			SOW Para 3.3		MCLBA	(583-	1)		TOTAL PRICE
7. DD 250 REQ	9. DIST STATEMENT REQUIRED	10. FREQUENC		12. DATE OF FIRST SUBMISSI		14. DISTRIBUTION				
LT		11. AS DF DAT	SREQ	SEE BLK 13. DATE OF SUBSEQUENT	10			b. COPIES		
8. APP CODE	Α	11. AS UF DAT	·	SUBMISSION		a. ADDRESSEE	Draft	Fir Reg	Repro	
Blk 4 - Contractormat.	ctor format is autl	horized a	nd shall be sul	omitted in .doc or	.pdf	MCLBA (583-1)	0	1	0	
Blks 10 & 12 - nonconforming documentation	RFDs shall be su material which o	ibmitted to loes not r	to obtain authoneet prescribe	orization to delive d configuration	r					
	eviewed and disp Government.									
RFDs shall be mbmatcomcon	transmitted via E- figmngmnt@mate	-Mail to toom.usmo	he following a mil	address:						
Distribution St	atement A: Appr	oved for	public release	, distribution is u	nlimited.					
										:
I									-	
										: - - -
										: 
										i 
<u>                                       </u>						15. TOTAL	0		0	
G. PREPARED BY	PRAID	1/1	H. DATE	I. APPROVED B	w	Last	J. DAT	e April	)3	: :
DD FORM 1423-	1, AUG 96 (EG)	1	PR	EVIOUS EDITION MAY BE	USED.		Page	of	Pages	: